

AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT

1. CONTRACT ID CODE

PAGE

OF PAGES

1

1

2. AMENDMENT/MODIFICATION NO.

0001

3. EFFECTIVE DATE

02/02/2011

4. REQUISITION/PURCHASE REQ. NO.

5. PROJECT NO. (If applicable)

6. ISSUED BY

DOT/FEDERAL AVIATION ADMINISTRATION
SOUTHERN REGION, ASO-52
1701 COLUMBIA AVENUE
COLLEGE PARK, GA 30337

7. ADMINISTERED BY (If other than Item 6)

SAME AS BLOCK 7
Maxine L. Peace

8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and ZIP Code)



9A. AMENDMENT OF SOLICITATION NO.

DTFAEN-11-R-00026

9B. DATED (SEE ITEM 11)

01/21/2011



10A. MODIFICATION OF CONTRACT/ORDER NO.

*TO BE COMPLETED BY VENDOR IF NOT COMPLETE
CODE

FACILITY CODE

10B. DATED (SEE ITEM 13)

11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS



The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offer is ☐ extended ☒ is not extended.

Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation on as amended, by one of the following methods:

(a) By completing Item 8 and 15, and returning _____ copies of the amendment; (b) acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hours and date specified.

12. ACCOUNTING AND APPROPRIATION DATA (If required)

13. THIS ITEM APPLIES ONLY TO MODIFICATIONS OF CONTRACTS/ORDERS, IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.

A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT/ORDER NO. IN ITEM 10A.



B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation data, etc.) SET FORTH IN ITEM 14.



C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF:



D. OTHER (Specify type of modification and authority)

E. IMPORTANT: Contractor ☒ is not, ☐ is required to sign this document and return _____ copies to the issuing office.

14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.)

RE: ELEVATOR REFURISHMENTS: FLO, MYR and GSO.

Attached are Questions and Responses related to the Scope of Work and existing conditions.

Word Document, sump pump floor plan and photo.

THERE ARE NO FURTHER CHANGES TO AMENDMENT 0001

15A. NAME AND TITLE OF SIGNER (Type or print)

16A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print)

MAXINE L. PEACE

15B. CONTRACTOR/OFFEROR

15C. DATE SIGNED

16B. UNITED STATES OF AMERICA

16C. DATE SIGNED

(Signature of person authorized to sign)

BY

(Signature of Contracting Officer)

02/02/2011

QUESTION 1:

Scope for Florence ATCT states that the existing elevator sump pump is to be replaced in addition to a new back-up sump pump installation, with battery back-up & accessories. There is no existing sump pit or pump in the elevator shaft (see attached photo of FLO ATCT Elevator Pit). In order to install scope items 49, and 50, the basin of the pit would require demolition/excavation to create a sump pit in the concrete shaft basin. Is this what the FAA desires?

Response 1:


Florence ATCT elevator sump pump is to be mounted within the equipment room area with a remove float switch and piped suction line in the corner of the existing pit. Outlet will be routed to exterior wall through the equipment room. See attached sketch RFI-001

QUESTION 2:

Scope for Myrtle Beach ATCT states a requirement for a 5-year load test, scope item 13, to be performed on the hydraulic elevator system. The 5-year load test is normally on performed on traction type elevators, not hydraulic elevators. Would a pressure test be more suitable?

Response 2:

At Myrtle Beach ATCT, delete requirement for a 5 year load test and provide for a hydraulic pressure test.



Sketch RFI-001
FLO ATCT Ground Level Floor Plan
Feb 2, 2011 FAA ATO ES

PROVIDE FLOOR ON 40' TOWER

Suction Line to pit with remote float switch activation


PROVIDE COMPLETE WALLS IN 40' TOWERS

PRECAST CONC. SPLASH BLOCK

ELEVATOR EQUIPMENT & WIRE FENCE ONLY IN TOWERS 50' & OVER IN HGT. (SEE DWG. AG)

Discharge line to exterior

Sump Pump mounted on wall bracket



2 C-1 LEVEL
SCALE: 3/8"=1'-0"

